COMMONWEALTH OF VIRGINIA DEPARTMENT OF ENVIRONMENTAL QUALITY SOURCE INSPECTION REPORT FORM



I. GENERAL INFORMATION	
SOURCE NAME: NORFOLK & WESTERN (NS)	REGISTRATION NO.: 60180
LOCATION: LAMBERTS POINT YARD NORFOLK	INSPECTION DATE: Jan. 24, 1995
COUNTY NO.: 710 PLANT ID: 00048	SOURCE CLASS: <u>A1</u>
SOURCE CONTACT: Mr. Jerry R. Gray / Steve Austin	
WEATHER CONDITIONS: Cold; windy; clear	
TYPE OF INSPECTION:	
X SCHEDULED INSPECTION	PERMIT COMPLETION
FOLLOW-UP INSPECTION	COMPLAINT INVESTIGATION
OTHER (EXPLAIN)	
ANNOUNCED INSPECTION: NO_	
INSPECTION LEVEL PERFORMED 2 COMPLIAN	NCE CODE 3
VEE PERFORMED <u>YES</u> INDICATES COMPLIANCE <u>Y</u>	<u>res</u>
OPERATING RATE: <u>All boilers / ship loading</u>	
INSPECTOR: Williams, W STAFF CODE 932	
CODING INFORMATION FOR COMPLIANO	CE STATUS
0 - UNKNOWN 1 - IN VIOLATION - NO SCHEDULE 2 - IN COMPLIANCE BY SOURCE TEST 3 - IN COMPLIANCE BY INSPECTION 4 - IN COMPLIANCE BY CERTIFICATION 5 - IN VIOLATION, MEETING SCHEDUL 7 - IN VIOLATION, UNKNOWN WITH R	E 9 - IN COMPLIANCE, CLOSED EDULE
II. INSPECTION SUMMARY	
<u>NO</u> Were actual or potential compliance problems	s identified during this inspection
NO COMPLAINTS: Are compliance problems indicat	ted?
NO Does source experience excessive malfunction	ns? If yes, describe:
NO Has any enforcement action been initiated dur	ring the past two years?
NO Is inspection needed due to on-going or rece	ently completed enforcement?
NO Is there an on-going compliance problem? If	yes, describe:
NO Are there compliance problems involving more system?	e than one control or process
Are all compliance problems indicated above	minor?

•	INSPECTION SUMMARY (CONTINUED)	PAGE	2
	If yes, are all compliance problems identified above now resolved?		
	NO Is a follow-up inspection needed?		
	Rate control equipment/process vulnerability to upset: Very High High Averagex_ Low		
	Rate O & M practices at the site: Very High High Averagex Low		
	3 Rank the source from 1 (lowest priority) to 4 (highest priority) for a inspection next year based on your overall evaluation of the source:	n	
•	INSPECTION COMMENTS		
	BOILERS:		
	(2) small boilers (just over 1 MMBTU) and (2) hot air heaters (< 1 MMBTU) heat for office and shop space. All units cycled on and off during inspec No. 2 F.O. is used. No operating data available. A Method 9 was taken at Superintendents Bldg. All other units show 0% opacity while running.	tion.	
	FUGITIVE COAL DUST EMISSIONS :		
	- The rotary railcar coal dumping operation was down temporarily and was n observed.	ot	
	 Ship loading systems and coal storage surge silos were in operation with visible emissions noted at the hooded conveyors and (10) coal transfer p Baghouse stacks (atop the > 100 ft. silos) and the ship loading port sec observed from ground level with binoculars. No visible emissions noted BGHSE stacks. 	oints. tion was	
	- The pier (6) loading area needed sweeping but very little dust was stirr	ing.	
	RECORDS:		
	Required for control equipment operating parameters; maintenance schedule; monthly coal throughput for conveying systems. The assistant general form Wayne Henley was not available for review of these records. A follow-up in late spring or early summer ('95) will accomplish the record review.	an, Mr.	n
	NEW CONSTRUCTION:		
	Two (2) waste water treatment towers are under construction to process the from the locomotive diesel shop. This is a modification of the process.	run off	
	No compliance problems were indicated during this inspection.		
SP	ECTOR'S SIGNATURE /// /// // DATE: January 25	, 1995	
PΕ	RVISOR'S COMMENTS:		

OCR

The following pages contain the Optical Character Recognition text of the preceding scanned images.

COMMONWEALTH OF VIRGINIA
DEPARTMENT OF ENVIRONMENTAL QUALITY
SOURCE INSPECTION REPORT FORM

1. GENERAL INFORMATION

SOURCE NAME: NORFOLK & WESTERN (NS) REGISTRATION NO.: 60180

LOCATION: LAMBERTS POINT YARD NORFOLK INSPECTION DATE: Jan. 24, 1995

COUNTY NO. : 710 PLANT ID: 00048 SOURCE CLASS: Al

SOURCE CONTACT: Mr. Jerry R. Gray I Steve Austin

WEATHER CONDITIONS: Cold; windy; clear

TYPE OF INSPECTION:

X SCHEDULED INSPECTION PERMIT COMPLETION

FOLLOW-UP INSPECTION COMPLAINT INVESTIGATION

OTHER (EXPLAIN)

ANNOUNCED INSPECTION: NO

INSPECTION LEVEL PERFORMED -2 COMPLIANCE CODE 3

VEE PERFORMED -YES INDICATES COMPLIANCE YES

OPERATING RATE: All boilers I ship loading

INSPECTOR: Williams, W STAFF CODE 932

CODING INFORMATION FOR COMPLIANCE STATUS-

- 0 UNKNOWN 4 IN COMPLIANCE BY CERTIFICATION 8 NO APPLICABLE REGULATION 1 IN VIOLATION NO SCHEDULE 5 IN VIOLATION, MEETING SCHEDULE 9 IN COMPLIANCE, CLOSED
- 2 IN COMPLIANCE BY SOURCE TEST 6 IN VIOLATION, NOT MEETING SCHEDULE
- 3 IN COMPLIANCE BY INSPECTION 7 IN VIOLATION, UNKNOWN WITH RESPECT TO SCHE DULE

II. INSPECTION SUMMARY

NO_ Were actual or potential compliance problems identified during this inspection?

- NO_ COMPLAINTS: Are compliance problems indicated?
- NO_ Does source experience excessive malfunctions? If yes, describe:
- NO Has any enforcement action been initiated during the past two years?
- NO_ Is inspection needed due to on-going or recently completed enforcement?
- NO_ Is there an on-going compliance problem? If yes, describe:
- ${\tt N0}_{\tt Are}$ there compliance problems involving more than one control or process system?

Are all compliance problems indicated above minor?

11. INSPECTION SUMMARY (CONTINUED) PAGE 2

If yes, are all compliance problems identified above now resolved?

NO Is a follow-up inspection needed?

Rate control equipment/process vulnerability to upset: Very High High Average x Low

Rate 0 & M practices at the site: Very High High Average x Low

3 Rank the source from I (lowest priority) to 4 (highest priority) for an inspection next year based on your overall evaluation of the source:

II. INSPECTION COMMENTS

BOILERS :

(2) small boilers (just over 1 MMBTU) and (2) hot air heaters (< I MMBTU) provide heat for office and shop space. All units cycled on and off during inspection.

No. 2 F.O. is used. No operating data available. A Method 9 was taken at the Superintendents Bldg. All other units show 0% opacity while running.

FUGITIVE COAL DUST EMISSIONS :

- The rotary railcar coal dumping operation was down temporarily and was not observed.
- Ship loading systems and coal storage surge silos were in operation with min imal

visible emissions noted at the hooded conveyors and (10) coal transfer points.

Baghouse stacks (atop the. > 100 ft. silos) and the ship loading port section was observed from ground level with binoculars. No visible emissions noted at the BGHSE stacks.

- The pier (6) loading area needed sweeping but very little dust was stirring.

RECORDS

Required for control equipment operating parameters; maintenance schedule; and

monthly coal throughput for conveying systems. The assistant general forman, Mr .

Wayne Henley was not available for review of these records. A follow-up inspection

in late spring or early summer ('95) will accomplish the record review.

NEW CONSTRUCTION

Two (2) waste water treatment towers are under construction to process the run off from the locomotive diesel shop. This is a modification of the process.

No compliance problems were indicated during this inspection.

INSPECTOR'S SIGNAJAfftE-.-. -.___'@@/ DATE: January 25, 1995

SUPERVISOR'S COMMENTS:

,SUPE"ISOR'S SIGNATURE DATE