

Pinzel, Kenneth (DEQ)

From: Wesley Simon-Parsons [WParsons@dominionterminal.com]
Sent: Monday, December 07, 2015 10:58 AM
To: Pinzel, Kenneth (DEQ)
Subject: Fwd: PM10 Upticks
Attachments: image001.jpg

Just a follow up

Wes
(757) 912-4291

Begin forwarded message:

From: "Steil, Cory" <Cory_Steil@kindermorgan.com<mailto:Cory_Steil@kindermorgan.com>>
Date: December 7, 2015 at 10:54:03 EST
To: Wesley Simon-Parsons
<WParsons@dominionterminal.com<<mailto:WParsons@dominionterminal.com>>>
Subject: RE: PM10 Upticks

Wes,
Looking through past records I don't see anything that stands out. All of our environmental controls were in service and cycles completed as required. On May 11 we show rainfall of 0.58" during the day, don't see how an uptick would be possible? I'm sure the HRSD project didn't help any with pavement sawing, excavations, equipment traffic/emissions, one phase of the HRSD project was conducted right next to your filters!

From: Steil, Cory
Sent: Monday, December 07, 2015 7:12 AM
To: 'Wesley Simon-Parsons'
Subject: RE: PM10 Upticks

I will look into it. What's going on?

From: Wesley Simon-Parsons [<mailto:WParsons@dominionterminal.com>]
Sent: Sunday, December 06, 2015 10:58 AM
To: Steil, Cory
Subject: PM10 Upticks


Can you see anything in your records that would explain an uptick in PM10 3/30-3/31 or 5/11-5/12?

Weren't they still working on the sewer line replacement at that time?

Wesley Simon-Parsons, P.E., M.ASCE
Engineering Manager
Dominion Terminal Associates, LLP
600 Harbor Rd, Newport News, VA
D: (757) 926-0937
F: (757) 247-9729

[FOC.JPG]

PM-10 Concentration Measured by Monitor near NN Coal Terminals



4478
Lbb09