

COMMONWEALTH OF VIRGINIA
DEPARTMENT OF AIR POLLUTION CONTROL
SOURCE INSPECTION REPORT FORM

I. GENERAL INFORMATION

SOURCE NAME Domtaron Terminal REGISTRATION NO. 60997
LOCATION TERMINAL KLVDP NPN INSPECTION DATE 020394
COUNTY NO. 700 PLANT ID 00074 SOURCE TYPE COAL STORAGE

SOURCE CLASS (CIRCLE ALL APPLICABLE CLASSES) A1 A2 B NSPS PSD NESHAP TOXIC

SOURCE CONTACT MR Tom Nock WEATHER CONDITIONS FAIR/COOL

TYPE OF INSPECTION

- SCHEDULED INSPECTION
 FOLLOW-UP INSPECTION
 OTHER (EXPLAIN) _____

- PERMIT COMPLETION
 COMPLAINT INVESTIGATION

ANNOUNCED INSPECTION (CIRCLE ONE) YES NO

INSPECTION LEVEL PERFORMED (CIRCLE ONE) 0 1 2 3 4 COMPLIANCE CODE 3

VEE PERFORMED (CIRCLE ONE) YES NO INDICATES COMPLIANCE (CIRCLE ONE) YES NO

OPERATING RATE SEE ATTACHED

INSPECTOR J.E. STEWART

STAFF CODE 789

CODING INFORMATION FOR COMPLIANCE STATUS

0 - UNKNOWN
1 - IN VIOLATION - NO SCHEDULE
2 - IN COMPLIANCE BY SOURCE TEST

3 - IN COMPLIANCE BY INSPECTION
4 - IN COMPLIANCE BY CERTIFICATION
5 - IN VIOLATION, MEETING SCHEDULE

6 - IN VIOLATION, NOT MEETING SCHEDULE
7 - IN VIOLATION, UNKNOWN WITH RESPECT
TO SCHEDULE
8 - NO APPLICABLE STATE REGULATIONS
9 - IN COMPLIANCE, CLOSED

II. INSPECTION SUMMARY

Were actual or potential compliance problems identified during this inspection? YES NO (If yes explain in comments section.)

Complaints: Are compliance problems indicated? YES NO (If yes, explain in the comment section.)

Does source experience excessive malfunctions? YES NO If yes, describe: _____

Has any enforcement action been initiated during the past two years? YES NO

Is inspection needed due to on-going or recently completed enforcement? YES NO

II. INSPECTION SUMMARY (CONTINUED)

PAGE 2

Is there an on-going compliance problem? YES NO If yes, describe:

Are there compliance problems involving more than one control or process system?
YES NO *N/A*

Are all compliance problems indicated above minor? YES NO *N/A*

If yes, are all compliance problems identified above now resolved?
YES NO *N/A*

Is a follow-up inspection needed? YES NO

Rate control equipment/process vulnerability to upset:
Very High High Average Low

Rate O & M practices at the site:

Very High High Average Low

Rank the source from 1 (lowest priority) to 4 (highest priority) for an inspection next year based on your overall evaluation of the source: 2

III. INSPECTION COMMENTS: Source was dumping and laying out coal onto piles at 1000 T/h. The ship "Magel Pride" was being top-off. The visual emission from transfer points, silo baghouses, & coal piles. (See VEER on baghouse silo). Control system was just coming on line from freeze condition. (See attached) A 18.94 kg/m³ plate out of 1000. Under normal conditions i.e. T°F 29 valve would have been 10.99 with an efficiency of 88.78%

ADDITIONAL COMMENTS? YES (See Page(s)) NO

INSPECTOR'S SIGNATURE _____

DATE: / /

SUPERVISOR'S COMMENTS: _____

SUPERVISOR'S SIGNATURE _____

DATE: / /

III. INSPECTION COMMENTS (CONTINUED)

PAGE 2

SOURCE NAME: Demaresta Terminal -

REGISTRATION NO 00074

LOCATION: TERMINAL BLVD.


INSPECTION DATE 02/03/94

COMMENTS (CONTINUED):

for the day. Co is efficient
was 79.40% with more cycles than necessary
due to post freeze pull out.

INSPECTOR'S SIGNATURE

SUPERVISOR'S SIGNATURE



DATE: 02/08/94

DATE: 2/12/94

OCR

The following pages contain the Optical Character Recognition text of the preceding scanned images.

COMMONWEALTH OF VIRGINIA
DEPARTMENT OF AIR POLLUTION CONTROL
SOURCE INSPECTION REPORT FORM

I. GENERAL INFORMATION

SOURCE NAME TM ITT, T REGISTRATION NO.

LOCATION, INSPECTION DATE

COUNTY NO. PLANT ID SOURCE TYPE 06--@'q Z, 12.* e7

SOURCE CLASS (CIRCLE ALL APPLICABLE CLASSES) A1 (B NSPS PSD NESHAP TOXIC

SOURCE CONTACT Zt@') <__ WEATHER CONDITIONS

TYPE OF INSPECTION

all' -s"CHEDULED INSPECTION PERMIT COMPLETION

F-I FOLLOW-UP INSPECTION F-I COMPLAINT INVESTIGATION

OTHER (EXPLAIN) YES (N::0)

ANNOUNCED INSPECTION (CIRCLE ONE)

INSPECTION LEVEL PERFORMED (CIRCLE ONE) 0 1 3 4 COMPLIANCE CODE F7

VEE PERFORMED (CIRCLE ONE) 0@ (ED NO E.S,1@ NO INDICATES COMPLIANCE (CIRCLE ONE)

.--?: C- ,//, 6 -- 4)

OPERATING RATE @=)

(@)___ INSPECTOR) STAFF CODE

CODING INFORMATION FOR COMPLIANCE STATUS

0 - UNKNOWN 3 - IN COMPLIANCE BY INSPECTION 6 - IN VIOLATION, NOT MEETING SCHEDULE

1 - IN VIOLATION - NO SCHEDULE 4 - IN COMPLIANCE BY CERTIFICATION 7 - IN VIOLATION, UNKNOWN WITH RESPECT

2 - IN COMPLIANCE BY SOURCE TEST 5 - IN VIOLATION, MEETING SCHEDULE TO SCHEDULE

8 - NO APPLICABLE STATE REGULATIONS

9 - IN COMPLIANCE. CLOSED

II. INSPECTION SUMMARY

Were actual or potential compliance problems identified during this inspection? YES No t-1, (If yes explain in comments section.)

Complaints: Are compliance problems indicated? YES NO (If yes, explain in the comment section.)

Does source experience excessive malfunctions? YES No '_@` If yes, describe:

Has any enforcement action been initiated during the past two years? YES NO

Is inspection needed@e@to on-going or recently completed enforcement? YES NO

II. INSPECTION SUMMARY k. (CONTINUED)
PAGE 2

Is there an on-going compliance problem? YES NO If yes, describe:

Are there compliance problems involving more than one control or process system?
YES NO

Are all compliance problems indicated above minor? YES NO @16111111f

If yes, are all compliance problems identified above now resolved?
YES NO

Is a follow-up inspection needed? YES NO

Rate control equipment/process vulnerability to upset:
Very High High Average Low

Rate O & M practices at the site:
Very High High Average Low

Rank the source from 1 (lowest priority) to 4 (highest priority) for an inspection
next year based on your overall evaluation of the source:

III. INSPECTION COMMENTS:
-7-

e2-

/-7 I ., >
I/ 64 7e
ADDITIONAL COMMENTS? YES (See Page(s) NO
INSPECTOR'S SIGNATURE DATE:
SUPERVISOR'S COMMENTS:

SUPERVISOR'S SIGNATURE DATE:

III. INSPECTION COMMENTS (CONTINUED) PAGE

ln@v
SOURCE NAME: REGISTRATION NO

LOCATION: INSPECTION D lf@@ L3 IcA
'A

COMMENTS (CONTINUED)- ; , -- , \

INSPECTOR'S SIGNATURE DATE:
SUPERVISOR'S SIGNATURE DATE: