

Page

Commonwealth of Virginia

Registration No: 60997

AFS Plant ID: 700-00074

Plant Name:

Dominion Terminal Associates

Classification: Synthetic Minor

Address:

Pier 11 Harbor Rd

Region: TRO

Report No:

254008

AIR INSPECTION REPORT

Inspection Date:

07/28/08

Contact Name:

Dan R Wagoner

Type:

PCE Without Site Visit

Contact Phone No: (757)245-2275

Inspector:

Kenneth J Pinzel

Air Program

Subpart

Inspection Result: In Compliance

SIP

Reason:

Conduct Enforcement Follow-up (off-site)

Inspector Comments:

A Request for Corrective Action was written frequency of checking for malfunctioning rainbirds and delay in truncating and compacting piles. The response is deemed adequate.

2 Jingel

Inspector's Electronic Signature Approval Date: Jul 28, 2008

Manager's Electronic Signature Approval Date: 7/30/08



Commonwealth of Virginia

Registration No: 60997

AFS Plant ID:

700-00074

Plant Name:

Dominion Terminal Associates

Classification:

Synthetic Minor

Address:

Pier 11 Harbor Rd

Region:

TRO

Report No:

254008

INSPECTION CHECKLIST				
Permit Date or Basis	#	Requirement Narrative	Observation	Comp
09-20-06	9	9. FUGITIVE DUST EMISSION CONTROLS - All storage piles shall be truncated, stacker/reclaimers used to build flat top piles, and the top compacted to minimize fugitive emissions.	as soon as practical after	In Compliance
09-20-06	8	8. FUGITIVE DUST EMISSION CONTROLS - Fugitive dust emissions from the storage piles shall be controlled by a wet suppression system capable of wetting the entire storage area. Wet suppression cycles shall be implemented in accordance with Appendix A. Each cycle shall consist of no less than 35,500 gallons of water and, with assistance from other equipment, attain 100 percent coverage of the storage area. The wet suppression system shall be provided with adequate access for inspection.	they will place additional emphasis on the importance of observing and reporting "out-	

OCR

The following pages contain the Optical Character Recognition text of the preceding scanned images.

Run-date 07/28/2008 05:17 PM Page 1 of 2 NW VIRGI= TMENTOF ENVIRONMENTAL QUALITY Commonwealth of Virginia

Registration No: 60997 AFS Plant ID: 700-00074

Plant Name: Dominion Terminal Associates Classification:, Synthetic Minor

Address: Pier 11 Harbor Rd Region: TRO

Report No: 254008

AIR INSPECTION REPORT

inspection Date: 07/28/08 Contact. Name: Dan R Wagoner Type: PCE Without Site Visit Contact Phone No: (757)245-2275

inspector: Kenneth J Pinzel Air Program Subpart

Inspection Result: In Compliance SIP

Reason:

Conduct Enforcement Follow-up (off-site)

inspector Comments:

A Request for Corrective Action was written frequency of checking for malfunct ioning

rainbirds and delay in truncating and compacting piles. The response is deeme d adequate.

Inspector's Electronic Signature Managerlm Electronic Signature Approval Date: Jul 28, 2008 Approval Date: -7130?

Run Date: 0-i/28/2008 05:17 PM Page 2 of 2

IIRGINLA DEPARTMENT 0 ENVIRONMENTAL QUALITY

Conunonwealth of Virginia

Registration No: 60997 APS Plant ID: 700-00074

Plant Name: Dominion Terminal Associates Classification: Synthetic Minor

Address: Pier 11 Harbor Rd Region: TRO

Report No: 254008

INSPECTION CHECKLIST

Permit Date Comp or Basis Requirement Narrative observation Status

09-20-06 9 9. FUGITIVE DUST EMISSION CONTROLS In their response, they said In
- All storage piles shall be they will place additional Compliance
truncated, stacker/reclaimers used emphasis on truncating piles
to build flat top piles, and the as soon as practical after
top compacted to minimize fugitive their profiles are modified.
emissions.

09-20-06 8 8. FUGITIVE DUST EMISSION CONTROLS In their response, they said In - Fugitive dust emissions from the they will place additional Compliance storage piles shall be controlled emphasis on the importance of by a wet suppression system capableobserving and reporting "out-of wetting the entire storage area. of-service" rainbirds and Wet suppression cycles shall be placing a high priority on implemented in accordance with repair.

Appendix A. Each cycle shall consist of no less than 35,500

gallons of water and, with assistance from other equipment, attain 100 percent coverage of the storage area. The wet suppression system shall be provided with adequate access for inspection.